

CRANE WIRE FAILURE AND AFTERMATH

01 February 2023

The Vessel



Vessel Particulars

- Built – 2010 Linhai, China
- Vessel Type: Handy Bulk Carrier
- GT: 20,867 tons
- Summer DWT: 32,593 tons
- LOA: 180 m
- Beam: 28 m
- Summer Draught: 10.17 m
- Cranes: 4 x 30.5 MT SWL

Location

- Port Kembla
- Port side alongside
- Berth 109 – BlueScope terminal

The Incident

Stevedore lifted steel coil from shore to vessel at 09:30hrs
1st Feb 2023

When beginning to swing across deck noises were heard that indicated possible wire failure, crane operator reversed the swing back towards the berth. The lifting wire then parted dropping the 22 tonne steel coil onto the wharf


It hit the wharf after first striking a steel coil in position waiting its turn to be loaded. By first impacting the coil, substantial wharf damage was avoided

As a precaution, the underside and greater wharf structure were examined before work recommenced (by engineers)

All stevedores were following safe work practices and were outside lifting exclusion zones

As is their standard practice, stevedores inspected all wires and cranes before first use this port

Observations by Berth Operator




The photo shows what the arrangement should have looked like prior to the lift

The coil on the left was the one being lifted


It dropped onto the coil on the right, spinning it around approx. 90deg and pushing the concrete barrier away from beside it

The coil that fell then hit the barrier that was between the coils and pushed it out in the other direction, with the coil that fell landing on its face on the berth

Exclusion zone for personnel meant that no-one was injured







Investigation by Stevedore



Crane Operator was in the process of lifting 21t rolled steel coil from Port Kembla berth 109 into ship's hold #4 on the vessel using ships crane #4 when the coil fell back to wharf



Visual inspections of the vessel crane and lifting wire by a competent person did not identify any defect, damage or concern prior to commencement of lifting operations




The vessel crane wire parted (failed) during normal use in line with the certified Working Load Limit of the plant



Post incident visual inspection of the broken crane wire strands is indicative of internal corrosion of the crane lifting wire

The Coil Landing on Another Coil Reduced Damage to the Wharf






The Crane Hook and Coil Lifting Cradle Cracked Concrete







Root Cause Determined by Stevedores







Investigation Revealed Much More

Vessel operator had only fairly recently taken over the vessel

Onboard records showed the lifting wire for the 30.5 tonne rated, No.4 cargo crane was renewed July 2019 (previous vessel operator)

Circumstances relating to the sourcing of wire and how it was stored/ stowed and cared for up until use onboard – not investigated / determined

Cargo lifting equipment last annual Survey by Class – Sept 2022 (Incident 01 Feb 2023)

Spec' sheet for surface lubricant indicated same lubricant was also suitable for open gear and chain drives, giving the impression it was a surface lubricant, not a penetrating grease

Both lubricant types are used on wires, but the application from time to time of a wire penetrating lubricant is required, not just surface lubrication of wires

Previous operators' maintenance regime for ships cranes not determined

Noting other factors of their intention to remove the vessel from their fleet, maintenance may not have been fully upheld, further noting not investigated/ proven



Root Cause

03 Feb 2023 examination of parted wire – internals/ core dry and or corroded

Onboard evidence indicated same crane wire lubricant was in use by previous vessel operator had been using as onboard records showed, at least since 2010 (identical lubricant charts from oil/ lubricant supplier with dates listed on each)

Surface lubricant on wires was plentifully applied, at a minimum

Wire's core appeared dry and surface corrosion commonplace











What Worked

Presence of
Mind and Quick
Actions of
Crane Operator


Exclusion Zone
Around
Loading
Operations

Concrete
Barrier
Prevented Coil
Roll


Opportunities for Improvement?




Better Inspection of
Crane Wires by
Stevedores Prior Starting
Cargo



Vessel Planned
Maintenance for Wires
Including Replacement
Cycle



Consideration on
Ongoing Continuous
Maintenance Program
for Cranes



Questions??